

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SEW

Location ID: 335753

Date: 6/27/2024



**Location Entrance – Photo #01994**



**Wellheads – Photo #02006**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SENW

Location ID: 335753

Date: 6/27/2024



Separators – Photo #02002



Separator/Gas Meter – Photo #02003



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SENW

Location ID: 335753

Date: 6/27/2024



**Tank Battery – Photo #01995**



**Pit – Photo #02007**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SENW

Location ID: 335753

Date: 6/27/2024



Weathered/Illegible Battery Sign – Photo #01996



Stored Equipment – Photo #01998



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SENW

Location ID: 335753

Date: 6/27/2024



Stored/Unused Equipment – Photo #02001



Unused Equipment – Photo #02004



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SEW

Location ID: 335753

Date: 6/27/2024



Unused Equipment – Photo #02005



Open-Ended Line – Photo #01997



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/9SENW

Location ID: 335753

Date: 6/27/2024



Open-Ended Load Line – Photo #01999



Open-Ended Load Line – Photo #02000