

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL ALLEN POINT-66S95W/9NWSE

Location ID: 335626

Date: 6/27/2024



Location Entrance – Photo #02015



Wellheads – Photo #02017

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL ALLEN POINT-66S95W/9NWSE

Location ID: 335626

Date: 6/27/2024



Separators/Gas Meter – Photo #02037



Tank Battery – Photo #02027

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL ALLEN POINT-66S95W/9NWSE

Location ID: 335626

Date: 6/27/2024



Tank Battery – Photo #02030



Pit – Photo #02029

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL ALLEN POINT-66S95W/9NWSE

Location ID: 335626

Date: 6/27/2024



Stored Equipment – Photo #02020



Stored Equipment – Photo #02021

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL ALLEN POINT-66S95W/9NWSE

Location ID: 335626

Date: 6/27/2024



Stored Equipment – Photo #02024



Unused Equipment – Photo #02023

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL ALLEN POINT-66S95W/9NWSE

Location ID: 335626

Date: 6/27/2024



Open-Ended Offload Line – Photo #02019



Open-Ended Offload Line into Pit – Photo #02022

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL ALLEN POINT-66S95W/9NWSE

Location ID: 335626

Date: 6/27/2024



**Open-Ended Load Line – Photo #02036**