

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SEW

Location ID: 335661

Date: 6/27/2024



North End of Location – Photo #02039



Wellheads – Photo #02040

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SEW

Location ID: 335661

Date: 6/27/2024



Separators – Photo #02042



Tank Battery – Photo #02046

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SEW

Location ID: 335661

Date: 6/27/2024



Pit – Photo #02045



Open-Ended Load Line – Photo #02047

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AP-66S95W/10SENW

Location ID: 335661

Date: 6/27/2024



Open-Ended Load Line – Photo #02048