

Inspection Photos

07/08/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 316127

Inspection Doc: 696205952

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 316127



Photo 1: Photos from the Location. Location has met 1004 revegetation requirements. Note- photo right taken from adjacent to the access road, thus the lack of vegetation in the bottom of the photo.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 316127



July 8, 2024



July 8, 2024

Photo 2: Fence remaining along the perimeter of the Location. Fence requires removal for final passing.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources