

Inspection Photos

07/08/2024

Operator: PUCKETT LAND COMPANY #10341

Location ID: 316605

Inspection Doc: 696205954

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316605



Photo 1: Photos from the access road south of the Location, facing north.

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316605



Photo 2: Photos 2-3 taken from central areas of the Location. Photos provide an overview from north, east, south to west. Location has met 1004 revegetation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316605



Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316605



July 8, 2024



July 8, 2024

Photo 4: Fence remaining along the perimeter of the Location. Fence requires removal for final passing. Signage at Location entrance also requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources