

Inspection Photos

07/08/2024

Operator: PUCKETT LAND COMPANY #10341

Location ID: 316609

Inspection Doc: 696205956

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316609



Photo 1: Photos 1-2 taken from central areas of the Location. Photos provide an overview from north, east, south to west. Location has met 1004 revegetation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316609



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316609



Photo 3: Fence remaining along the perimeter of the Location. Fence requires removal for final passing. Signage at Location entrance also requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources