

Inspection Photos

07/08/2024

Operator: PUCKETT LAND COMPANY #10341

Location ID: 316610

Inspection Doc: 696205958

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316610



Photo 1: Photos 1-2 taken from central areas of the Location. Photos provide an overview from north, east, south to west. Location has met 1004 revegetation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316610



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316610



Photo 3: Signage remaining at Locations entrance. Signage requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316610




Photo 4: Photos examples showing Fence remaining along the perimeter of the Location; specifically, where the perimeter fence ties into the Surface Owner's pasture fence (dotted yellow line). Fence along the eastern perimeter of the Location (red) will require removal; fence to remain for the Surface Owner (yellow arrow) will need to be maintained.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: PUCKETT LAND COMPANY #10341

Location ID: 316610



Photo 5: Continued from photo 4. Photo 2023 Google Earth aerial imagery showing the Location's perimeter fence remaining. Fence outlined in red will require removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources