

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/32SENE

Location ID: 311555

Date: 6/28/2024



Location Entrance – Photo #02116



Wellheads – Photo #02117

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/32SENE

Location ID: 311555

Date: 6/28/2024



Separators – Photo #02123



Tank Battery – Photo #02124

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/32SENE

Location ID: 311555

Date: 6/28/2024



Open Wellhead Cellar – Photo #02118



Open Wellhead Cellar – Photo #02119

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/32SENE

Location ID: 311555

Date: 6/28/2024



Open Wellhead Cellar – Photo #02120



Open Wellhead Cellar – Photo #02121