

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**




When replaced additional information will be required



When replaced additional information will be required

KT Resources LLC
 WRD Unit 28-22
 Location ID: 316281



Calibration out of date

Equipment leak and stained soil

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



Debris



Unmarked anchor

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



Weeds




Weeds

KT Resources LLC
WRD Unit 28-22
Location ID: 316281



Containment crack



Damaged containment

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



Location from Southeast corner

Location from Northeast corner

**KT Resources LLC
WRD Unit 28-22
Location ID: 316281**



Location from Northwest corner



Location from Southwest corner