

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: State Antelope P-30 Pad**

**Loc ID: 433004**

**Inspection: 696306457**



Exhibit A



**Exhibit B**

**CA:** Tanks 220382 & 220381 NFPA and Capacity Labels have peeled off; no longer visible. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has reported that appropriate labels have been installed to comply with Rule 605.h.

**CA:** Trash and unused Wellhead Parts at Wellheads. Comply with Rule 606. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has reported that the identified debris/unused equipment has been appropriately removed to be in compliance with Rule 606.