

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 1 – 14-18 Well – Night Cap



Photo 2 – 14-18 Sign faded

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 3 – 13-18 Wellhead



Photo 4 – Sign Faded no longer visible

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 5 – 18C Wellhead



Photo 6 – Well Sign faded no longer visible

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 7 – 24-18 Wellhead



Photo 8 – Well Sign faded no longer visible

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 9 – 23-18 Wellhead



Photo 10 – Well Sign faded no longer visible

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 11 – Tank Battery



Photo 12 – Tank Battery Signs

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 13 – Separators



Photo 14 – Separators

Inspection Photos
Location Name: Antelope 18C PAD
Location ID: 418098



Photo 15 – Tank Battery – Backside