

Inspection Photos
Location Name: Antelope F-18 PAD
Location ID: 429686



Photo 1 – Pumping Units



Photo 2 – A-E-18HZ Wellsite

Inspection Photos
Location Name: Antelope F-18 PAD
Location ID: 429686



Photo 3 – Wellheads



Photo 4 – F-J-18HNB Sign Faded no longer visible

Inspection Photos
Location Name: Antelope F-18 PAD
Location ID: 429686




Photo 5 – Unused Parts and Unmarked 2" Riser at F-J-18HNB Wellhead



Photo 6 – K-O-18HNB Well Sign is starting to fade – Replace soon

Inspection Photos
Location Name: Antelope F-18 PAD
Location ID: 429686



Photo 7 – Separators



Photo 8 – A-E-18HN Separator Site

Inspection Photos
Location Name: Antelope F-18 PAD
Location ID: 429686



Photo 9 – Well Sign




Photo 10 – Unmarked Risers

Inspection Photos
Location Name: Antelope F-18 PAD
Location ID: 429686



Energy and Carbon Management Commission
40.40489, -104.37032, 4579.1ft
07/08/2024 11:57:46

Photo 11 – Tank Battery



Energy and Carbon Management Commission
40.40497, -104.37033, 4580.9ft
07/08/2024 11:57:55

Photo 12 – Tank Battery Signs

Inspection Photos
Location Name: Antelope F-18 PAD
Location ID: 429686



Photo 13 – Tank Battery Sign



Photo 14 – ECDs