

Inspection Photos
Location Name: Antelope 21-18
Location ID: 310865



Photo 1 – Lease Road looking East – Hot Wire

Photo 2 – No Drop Lines to access Lease Road to get to Wells

Inspection Photos
Location Name: Antelope 21-18
Location ID: 310865




Photo 3 – No Drop Lines to access Lease Road to get to Wells