

Final Reclamation and Stormwater Inspection

Date: 7/2/24

Operator: PDC Energy Inc - 69175

Location ID: 332807

Inspection Document #: 713900766

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dutton HD Pad 22-30D
Location ID: 332807



Photo 1. The photo was taken at the entrance to the well location facing North. The photo illustrates the outline of disturbance is apparent on the landscape with dominance of Kochia.



Photo 2. The photo was taken at the well location facing North. The photo illustrates the boundary and dominance of Kochia.

Note - The well location is in a fallow field at the time inspection.

Inspection Photos
Location Name: Dutton HD Pad 22-30D
Location ID: 332807



ECMC
89° E
7/2/24, 3:18 PM

Photo 3. The photo was taken at the well location facing East.
Refer to the comment for photo 2.



ECMC
177° S
7/2/24, 3:18 PM

Photo 4. The photo was taken at the well location facing South.
Refer to the comment for photo 2.



Inspection Photos
Location Name: Dutton HD Pad 22-30D
Location ID: 332807



Photo 5. The photo was taken at the well location facing West. Refer to the comment for photo 2.



Photo 6. The reference photo was taken near the well East of the well location facing East. The photo illustrates the field is currently fallow.

Note - Though fallow the field appeared to be dominated by Bluebunch wheatgrass.

Inspection Photos
Location Name: Dutton HD Pad 22-30D
Location ID: 332807



Photo 7. The photo was taken at the tank battery location. The photo illustrates the former tank battery location is stabilized with compact road base.