

Inspection Photos

API: 009-06583

Operator: NORSTAR PETROLEUM INC

Inspection Date: 6/13/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the former access road.



Inspection Photos



Photo 2. Facing west at the location. The crop has not re-established. Soil issues appear to be impacting crop growth.



Inspection Photos



Photo 3. Facing east at the location. The crop has not re-established. Soil issues appear to be impacting crop growth.



Inspection Photos



Photo 4. Facing north at the location. This area has no crop growth which is about 50'x50'.



Inspection Photos



Photo 5. Facing southeast toward the surrounding uniform crop cover in the reference area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources