

Inspection Photos
Location Name: LOUSTALET-65N64W/15NENE
Location #: 330519



Colorado Energy & Carbon Management Commission
Weld County
+40.404421, -104.529574
153° SE
2024-05-29 11:59

Photo #1
Loustalet 41-15 (123-19236) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 5 yds.
Unnecessary Equipment: Wellsite fencing
prior photo



Colorado Energy & Carbon Management Commission
Weld County
+40.403323, -104.526744
295° NW
2024-05-29 12:06

Photo #2
Loustalet 41-15 Battery site
Abandoned: MOST Equipment Removed
Plugged & Abandoned | PA
Wellsite / Battery entrance
prior photo



Inspection Photos

Location Name: LOUSTALET-65N64W/15NENE

Location #: 330519



Colorado Energy & Carbon Management Commission
Weld County
+40.404420, -104.529421
248° W
2024-07-10 13:36

Photo #3

Loustalet 41-15 (123-19236) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.

Wellsite fencing removed. CA: Resolved



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: LOUSTALET-65N64W/15NENE
Location #: 330519



Photo #4

Loustalet 41-15 Battery site

Abandoned: MOST Equipment Removed

Plugged & Abandoned | PA

**Unnecessary Equipment: Chemical pump equipment
prior photo**

Photo #5

Loustalet 41-15 Battery site

Abandoned: MOST Equipment Removed

Plugged & Abandoned | PA

**Unnecessary Equipment: Battery sign
prior photo**



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: LOUSTALET-65N64W/15NENE

Location #: 330519



Photo # 6

Loustalet 41-15 Battery site

Abandoned: ALL Equipment Removed

Battery sign, Chemical pump removed. CA: Resolved



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources