

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

07/11/2024

Document Number:

403851466

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10779 Contact Person: Spencer Jackson
Company Name: SCOUT ENERGY MANAGEMENT LLC Phone: (972) 965-5580
Address: 13800 MONTFORT DRIVE SUITE 100 Fax: ()
City: DALLAS State: TX Zip: 75240 Email: spencer.jackson@scoutep.com

Identification Information

API Number: 05 - - ECMC Facility ID: 102555 Initial Form 19 or 27 Document number:
Facility Name: COLLECTION STATION 22 Facility Number: Facility Type: PIT
Location QtrQtr: Section: 28 Township: 2N Range: 102W Meridian: 6
County: RIO BLANCO Field Name: RANGELY
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: SCOUT ENERGY MANAGEMENT LLC Agent Name: Spencer Jackson Title: Senior HSE Specialist
Phone Number: 972-965-5580 Email: spencer.jackson@scoutep.com

Rule 909.J Inspection Information

Date the Pit was Inspected 06/11/2024

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 102555 Facility Name: COLLECTION STATION 22 Facility Type: PIT
Location: QtrQtr: Sec: 28 Twp: 2N Range: 102W Meridian: 6
County Name: RIO BLANCO Latitude: 40.117420 Longitude: -108.852554

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 120601 Document Name: Collection Station 22-Chemical Analysis File Name: L1746396.xlsx
SampleType: Matrix:
Facility ID: 102555 Sample ID: 660223 Sample Name: Collection Station 22-Chemical Analysis Sample Date: 06/11/2024
Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Pace Analytical Lab Sample ID: L1746396-01

Batch ID: 120602	Document Name: Collection Station 22-TENORM Analysis	File Name: L1746422.xlsx
SampleType:	Matrix:	
Facility ID: 102555	Sample ID: 660224	Sample Name: Collection Station 22-TENORM Analysis
		Sample Date: 06/11/2024
Collection Point: SEP	Matrix: WATER	Pre Post: Rule 909.j subsequent sample
Project Number:	Remediation Number:	Complaint Number:
		NOAV Number:
Inspection Number:	Spill Number:	Laboratory: Pace Analytical
		Lab Sample ID: L1746422-01

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

User Group	Comment	Comment Date
Engineer	The data submitted by the operator can be accessed through COGIS data system.	07/11/2024
Total: 1 comment(s)		