

Inspection Photos
Location Name: EHRLICH-65N64W/5SWNW
Location #: 326884



Photo #1
Ehrlich #2 (123-13812) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 230 yds.



Photo #2
Ehrlich #2, #1 Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA
2: wells

