

Inspection Photos

June 28th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 322129

Inspection Document #: 714000913

Dolores County, CO

Township: NESW 6 40N 17W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DC 3
Location ID: 322129



Photo 1. View of project area taken from the southern edge facing north. Note: graveled area will remain as lined out in the BLM reclamation plan. Area to the west and east have been reclaimed and were assessed during this inspection.

Inspection Photos
Location Name: DC 3
Location ID: 322129

6/28/24
+37.756354,-108.770947
76° E



Photo 2. View of reclaimed area to the east of the graveled parking area. Note: area is dominated by desirable species.

Inspection Photos
Location Name: DC 3
Location ID: 322129



Photo 3. View of vegetation transects conducted on both the reclaimed areas and within the reference.

Inspection Photos
Location Name: DC 3
Location ID: 322129



Photo 4. View of reference area comprised of squirrel tail, gambel oak and pine.