

Inspection Photos

July 9th, 2024

Operator: Highpoint Operating Corporation -
10071

Location ID: 313631

Inspection Document #: 714000936

Montezuma County, CO

Township: SESE 28 38N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



7/9/24

+37.517960,-108.612435

342° N

Photo 1. View of the project area taken from the southern edge facing center.



Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



Photo 3. Cardinal photos taken from the center of the disturbance. Left photo facing south, right photo facing west. Note: Proper establishment of perennial vegetation appears to be affected by large patches of cheatgrass establishing in the center of the project area.

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631




Photo 4. Photos of vegetation transects conducted in both the project area (left) and reference area (right).

Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



Photo 5. View of wattle debris/trash left on the eastern side of the access road.



Inspection Photos

Location Name: Koskie 16H-28-38-16

Location ID: 313631



Photo 6. View of the reference area comprised of Crested wheatgrass, Western wheatgrass and Sandberg bluegrass.

