

Inspection Photos

July 9th, 2024

Operator: Highpoint Operating Corporation -
10071

Location ID: 313613

Inspection Document #: 714000938

Montezuma County, CO

Township: NENW 27 38N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Koskie-Brumley Draw 3H-27-38-16

Location ID: 313613

7/9/24

+37.529813,-108.605342

48° NE



Photo 1. View of the project area taken from the southern edge facing center. Note: Southwest corner/access point remains unreclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 083-06638

Inspection Photos

Location Name: Koskie-Brumley Draw 3H-27-38-16

Location ID: 313613



Photo 2. View of the access road that remains unreclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 083-06638

Inspection Photos

Location Name: Koskie-Brumley Draw 3H-27-38-16

Location ID: 313613



Photo 3. View of riser that remains in the center of the project area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 083-06638