

Inspection Photos

July 9th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 313545

Inspection Document #: 714000941

Montezuma County, CO

Township: NESE 36 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McElmo Dome Unit 36-37-18 MC 7
Location ID: 313545



7/9/24
+37.418976,-108.774107
341° N



7/9/24
+37.418618,-108.774433
29° NE

KINDER MORGAN
CO₂ COMPANY, LLC
McELMO DOME UNIT MC-7
SEC. 36, T37N, R18W
2215' FSL & 107' FEL
LEASE NO. C-27687
MONTEZUMA COUNTY, CO
EMERGENCY PHONE # 970-882-5522
OR 911

Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos

Location Name: McElmo Dome Unit 36-37-18 MC 7

Location ID: 313545



Photo 2. View of the northern interim reclamation area facing north west.



Inspection Photos

Location Name: McElmo Dome Unit 36-37-18 MC 7

Location ID: 313545



7/9/24

+37.418752,-108.774304

7° N

Photo 3. Cable debris corrective action identified in the previous inspection doc #693903599 has been addressed/resolved.

