

Inspection Photos

July 9th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 313490

Inspection Document #: 714000945

Montezuma County, CO

Township: SWSW 23 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McElmo Dome Unit 23-37-18 YB2
Location ID: 313490

7/9/24
+37.839726,-109.462292
322° NW



Photo 1. View of the well pad taken from the access point facing center.



API #: 083-06289

Inspection Photos

Location Name: McElmo Dome Unit 23-37-18 YB2

Location ID: 313490



7/9/24

+37.839726,-109.462292

251° W



Photo 2. View of the western portion of the interim reclamation area that remains mostly bare with sparse vegetation.

Inspection Photos

Location Name: McElmo Dome Unit 23-37-18 YB2

Location ID: 313490



7/9/24
+37.839726,-109.462292
37° NE

Photo 3. Reference are comprised of Crested wheatgrass, Rabbitbrush and juniper.

