

Field Inspection Photo Log

Date: 07/09/2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 317831

Inspection Document #: 708201406

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Location ID: 317831



Photo 1. Facing northwest at the Nessu 15 (123-07822) wellhead. CO List B Noxious Weed (musk thistle) observed to be growing around production equipment and undesirable vegetation (curly dock, prickly lettuce, and kochia) were also observed to be growing throughout the well location.

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



7/9/24, 2:35 PM
291° W
ECMC

Photo 2. Photo taken from the southeast portion of the well location. Undesirable vegetation observed to be growing around the well location.



Photo 3. Photo taken from the southwest portion of the well location. Undesirable vegetation observed to be growing around the well location.



Photo 4. Close up photo of undesirable vegetation growing in and around production equipment.

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Photo 5. Photo taken from the northwest portion of the well location. Undesirable vegetation observed to be growing around the well location.

Inspection Photos
Location Name: Nessu 15
Location ID: 317831



Photo 6. Photo taken from the northeast portion of the well location. Undesirable vegetation observed to be growing around the well location.