

Field Inspection Photos

Date: 07/09/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 305848

Inspection Document #: 708201403

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 1. Undesirable vegetation (kochia) observed near the Warner 4-18 (API 123-23565).

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 2. Facing southeast near the wellhead; see comments in Photo 1.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 3. Photo taken east of wellhead. Non-uniform vegetation cover observed near one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 4. Subsidence and undesirable vegetation (kochia) observed near one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 5. Non-uniform vegetation cover and undesirable vegetation (kochia) observed near one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 6. Subsidence, non-uniform vegetation cover and undesirable vegetation (kochia) observed at one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 7. Undesirable vegetation (kochia) observed at one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 8. Subsidence observed at one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 9. Subsidence observed at one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848



Photo 10. Undesirable vegetation (kochia) observed near one of the flowline potholes.

Inspection Photos
Location Name: Warner 4-18
Location ID: 305848




Photo 11. Google Earth aerial imagery taken circa (05/2023) illustrating flowline potholes (red outline) and evidence of non-uniform vegetation cover.