

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 07/11/2024 Document Number: 403851448

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10779 Contact Person: Spencer Jackson Company Name: SCOUT ENERGY MANAGEMENT LLC Phone: (972) 965-5580 Address: 13800 MONTFORT DRIVE SUITE 100 Fax: () City: DALLAS State: TX Zip: 75240 Email: spencer.jackson@scoutep.com

Identification Information

API Number: 05 - - ECMC Facility ID: 102557 Initial Form 19 or 27 Document number: Facility Name: RANGLEY WEBER STATION 17 Facility Number: Facility Type: PIT Location QtrQtr: Section: 29 Township: 2N Range: 102W Meridian: 6 County: RIO BLANCO Field Name: RANGELY Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: SCOUT ENERGY MANAGEMENT LLC Agent Name: Spencer Jackson Title: Senior HSE Specialist Phone Number: 972-965-5580 Email: spencer.jackson@scoutep.com

Rule 909.J Inspection Information

Date the Pit was Inspected 06/11/2024 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 102557 Facility Name: RANGLEY WEBER STATION 17 Facility Type: PIT Location: QtrQtr: Sec: 29 Twp: 2N Range: 102W Meridian: 6 County Name: RIO BLANCO Latitude: 40.115031 Longitude: -108.868826

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 120597 Document Name: Collection Station 17-Chemical Analysis File Name: L1746383.xlsx SampleType: Matrix: Facility ID: 102557 Sample ID: 660219 Sample Name: Collection Station 17-Chemical Analysis Sample Date: 06/11/2024 Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Pace Analytical Lab Sample ID: L1746383-01

Batch ID: 120598	Document Name: Collection Station 17-TENORM Analysis	File Name: L1746417.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 102557	Sample ID: 660220	Sample Name: Collection Station 17-TENORM Analysis
Collection Point: SEP	Matrix: WATER	Pre Post: Rule 909.j subsequent sample
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Pace Analytical
		NOAV Number: _____
		Lab Sample ID: L1746417-01

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	07/12/2024
Total: 1 comment(s)		