

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

07/11/2024

Document Number:

403851214

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

**Operator Information**

ECMC Operator Number: 10779 Contact Person: Spencer Jackson  
Company Name: SCOUT ENERGY MANAGEMENT LLC Phone: (972) 965-5580  
Address: 13800 MONTFORT DRIVE SUITE 100 Fax: ( )  
City: DALLAS State: TX Zip: 75240 Email: spencer.jackson@scoutep.com

**Identification Information**

API Number: 05 - - ECMC Facility ID: 463940 Initial Form 19 or 27 Document number:   
Facility Name: Collection Station 11 Facility Number: Facility Type: PIT  
Location QtrQtr: SWNW Section: 19 Township: 2N Range: 102w Meridian: 6  
County: RIO BLANCO Field Name: RANGELY  
Federal, Indian or State Lease Number:

## Information Submitted By:

Company Name: SCOUT ENERGY MANAGEMENT LLC Agent Name: Spencer Jackson Title: Senior HSE Specialist  
Phone Number: 972-965-5580 Email: spencer.jackson@scoutep.com

## Rule 909.J Inspection Information

Date the Pit was Inspected 06/11/2024

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 463940 Facility Name: Collection Station 11 Facility Type: PIT  
Location: QtrQtr: SWNW Sec: 19 Twp: 2N Range: 102w Meridian: 6  
County Name: RIO BLANCO Latitude: 40.129420 Longitude: -108.894588

**Sample Information:**

The following Sample Information has been reviewed by the ECMC:

Batch ID: 120587 Document Name: Collection Station 11- TENORM Analysis File Name: L1746412.xlsx  
SampleType: Matrix:  
Facility ID: 463940 Sample ID: 660209 Sample Name: Collection Station 11-TENORM Analysis Sample Date: 06/11/2024  
Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: Pace Analytical Lab Sample ID: L1746412-01

Batch ID: 120586	Document Name: Collection Station 11- Chemical Analysis	File Name: L1746375.xlsx
SampleType:	Matrix:	
Facility ID: 463940	Sample ID: 660208	Sample Name: Collection Station 11-Chemical Analysis      Sample Date: 06/11/2024
Collection Point: SEP	Matrix: WATER	Pre Post: Rule 909.j subsequent sample
Project Number:	Remediation Number:	Complaint Number:      NOAV Number:
Inspection Number:	Spill Number:	Laboratory: Pace Analytical      Lab Sample ID: L1746375-01

**Sample Facility Attachment:**

No Facility Attachment

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	07/12/2024
Total: 1 comment(s)		