

# Inspection Photos

Loc: 324565

Operator: SILVER MOUNTAIN ENERGY LLC

Inspection Date: 7/9/2024

County: HUERFANO



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north along the access road. There is noxious weeds along the road that need to be controlled. Red arrow points to Scotch thistle.




## Inspection Photos



**Photo 2.** Facing northwest toward the wellsite. The chemical barrel is tipped over and there is no secondary containment. No spills were observed.



## Inspection Photos



**Photo 3.** There are noxious weeds at the location that need to be controlled. Red arrow points to Plumeless/Scotch thistle.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324565 | Date: 7/9/2024