

Inspection Photos

Loc: 334513

Operator: SILVER MOUNTAIN ENERGY LLC

Inspection Date: 7/9/2024

County: HUERFANO



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. There is noxious weeds along the road that need to be controlled. Red arrow points to Scotch thistle.



Inspection Photos



Photo 2. Facing northeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334513 | Date: 7/9/2024

Inspection Photos



Photo 3. There are noxious weeds at the location that need to be controlled. Red arrow points to Plumeless thistle.

