

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2024

Submitted Date:

07/11/2024

Document Number:

715500395

**FIELD INSPECTION FORM**Loc ID 315682 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10556

Name of Operator: PLUG NICKEL OIL COMPANY INC

Address: PO BOX 1937

City: VERNAL State: UT Zip: 84078

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hogue, Lana	(435) 789-8479	hogue@stratanet.com	
Hogue, Jimmy	(435) 828-7666	hogue@stratanet.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231336	WELL	SI	01/01/2022	OW	103-09006	HILL 8	PA

**General Comment:****ECMC Inspection Report Summary**

On Thursday, 07/11/2024, Inspector Kirby Burchett, conducted a follow up field inspection from Plug and Abandon operations at Plug Nickel Oil Co. on the Hill 8 well, Location #316281, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

**Operations Summary:**

7/11/24. Verified cement top at surface.

7/10/24. Verify PBTD at 340'. Open hole to 280'. Surface casing 280' to surface, cemented to surface. Pumped 192 sacks cement filling open hole and surface casing to ground level. Shut down overnight for cement to set.

6/26/24. Plug back open hole with rock and sand to 340' from surface. Shut down waiting on cement availability.

All operations witnessed by Compliance Inspector.

No follow up inspection is required.

Inspected Facilities									
Facility ID:	231336	Type:	WELL	API Number:	103-09006	Status:	SI	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name:					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back: NO					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 340'					Cement Volume (sx): 192				
Good Return During Job: YES					Cement Type: C				
Comment: Filled open hole from 340' and 280' of surface casing to surface.									
Corrective Action:					Date:				

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12