

Inspection Photos

07/11/2024

Operator: UTAH GAS OP LTD DBA UTAH GAS
CORP - 10539

Location ID: 315642

Inspection Doc: 696205977

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315642



Photo 1: Photo taken from the south end of the Location, facing north. Vegetation observed within photo are predominantly Undesirable Plant Species including Houndstongue and Common Mullein.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315642



Photo 2: Photos example showing Undesirable Plant Species (Houndstongue) established throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315642



Photo 3: Photos example showing Undesirable Plant Species (Mullein) established throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP - 10539

Location ID: 315642



Photo 4: Photos examples showing that the access road has not been recontoured/regraded and reclaimed. Erosion degradation due to stormwater runoff observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources