


Operator: BCEI
Location Name: Antelope F-18
Loc ID: 429686
Inspection: 696306503



Antelope F-18

Exhibit A



Antelope F-18

Exhibit B




Exhibit C

CA: Unmarked Risers at A-E-18HZ Separator Site; see photos Comply with Rule 1105

CA Resolution: Operator has reported that the identified risers have now been appropriately marked to comply with Rule 1105.