

WELL NAME: BOWEN 34-34, API #: 071-07762, INSP. # 695109887



PHOTO 1: WELL SIGN



**PHOTO 2: LOCATION**







**PHOTO 3: WELLHEAD AND EQUIPMENT**







**PHOTO 4: OILY WASTE IN PRIME MOVE SKID HAS SPILLED OVER CAUSING IMPACT SOIL SURROUNDING SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULES 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 7-13-2024.**





**PHOTO 5: OILY WASTE IN PRIME MOVE SKID HAS SPILLED OVER CAUSING IMPACT SOIL SURROUNDING SKID. REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULES 1002..(2).D. CA DATE 8-13-2024.**







**PHOTO 6: OILY WASTE IN COMPRESSOR SKID HAS SPILLED OVER CAUSING IMPACT SOIL SURROUNDING SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULES 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 7-13-2024.**







**PHOTO 6: OILY WASTE IN COMPRESSOR SKID HAS SPILLED OVER CAUSING IMPACT SOIL SURROUNDING SKID. REPAIR ALL LEAKS AND REMOVE OR TREAT IMPACTED SOIL PER RULES 1002..(2).D. CA DATE 8-13-2024.**







**PHOTO 7: UNUSED EQUIPMENT (UNUSED 1" RISER NEAR COMPRESSOR SOUND WALLS). REMOVE OR MARK UNUSED RISERS PER RULE 606. CA DATE 8-12-2024.**