

WELL NAME: WAGNER 13-9 TR, API #: 071-09093, INSP. # 695109904



PHOTO 1: WELL SIGN





**PHOTO 2: LOCATION**







**PHOTO 3: WELLHEAD AND EQUIPMENT**







**PHOTO 4: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID, COMPRESSOR IS COVERED WITH A FILM OF OIL ALL OVER THE EQUIPMENT INDICATING SEVERAL LEAKS. REPAIR OR REPLACE LEAKING EQUIPMENT, REMOVE OR TREAT IMPACTED SOILS, Self-inspection, maintenance, and good housekeeping procedures and schedules PER RULE 1002..(2).D. CA DATE 8-13-2024.**

