

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

04/29/2024

Document Number:

403771814

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 95620 Contact Person: Steven James
Company Name: WESTERN OPERATING COMPANY Phone: (303) 726-8650
Address: 1165 DELAWARE STREET #200 Fax: ()
City: DENVER State: CO Zip: 80204 Email: steve@westenoperating.com

Identification Information

API Number: 05 - - ECMC Facility ID: 119666 Initial Form 19 or 27 Document number:
Facility Name: BOBCAT "D" UNIT Facility Number: Facility Type: PIT
Location QtrQtr: SWNW Section: 9 Township: 1S Range: 56W Meridian: 6
County: WASHINGTON Field Name: BOBCAT
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS, Inc. Agent Name: Drezden Kinnaird Title: Project Manager
Phone Number: 970-493-7780 Email: dkinnaird@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 04/01/2024
On inspection the Pit was: [X] Unlined [] Lined [X] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772371 Facility Name: BOBCAT "D" UNIT 909J FACILITY Facility Type: PIT
Location: QtrQtr: NWSW Sec: 9 Twp: 1S Range: 56W Meridian: 6
County Name: WASHINGTON Latitude: 39.985215 Longitude: -103.661823

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 118841 Document Name: EDD File Name: 2024_0401_Bobcat D Unit CGRS EDD AA06922 (1).xlsx
Sample Type: Matrix:
Facility ID: 772371 Sample ID: 658314 Sample Name: Sample Date: 04/01/2024
Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample
Project Number: 28154 Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Lab Sample ID: AA06922

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772371	403771841	2024_0401_BobcatDUnit_A A06922 (1).pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
658314	121-06551	BOBCAT D SAND UNIT 23	Rule 909.j subsequent sample
658314	121-06583	BOBCAT D SAND UNIT 20	Rule 909.j subsequent sample
658314	121-06592	BOBCAT D SAND UNIT 18	Rule 909.j subsequent sample
658314	121-06634	BOBCAT D-SAND UNIT 6	Rule 909.j subsequent sample

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	07/15/2024

Total: 1 comment(s)