

Inspection Photos
Location Name: BOX ELDER 1
Location ID: 320361



Photo #1 Crude & P/W tank.



Photo #2 Separator & weeds.

Inspection Photos
Location Name: BOX ELDER 1
Location ID: 320361



Photo #3 Well head.



Photo #4 Weeds on location.

Inspection Photos
Location Name: BOX ELDER 1
Location ID: 320361



Photo #5 Weeds on and inside berm and Graffiti on P/W tank.



Photo #6 Weeds on and inside berm and Graffiti on crude and P/W tanks.

Inspection Photos
Location Name: BOX ELDER 1
Location ID: 320361




Photo #7 Graffiti on Separator.



Photo #8 Weeds on and inside berm and Graffiti on crude tank..