

## Inspection Photos

Operator: VISION ENERGY LLC- 10770


Location Name: BEAR GULCH -FEDERAL #19-4

Location ID: 322362 API #: 05-045-06116

Inspection Date: 7/15/2024 Inspection Doc#: 693807483



Wellhead during MIT



Form 21 field copy



## Inspection Photos

**Operator: VISION ENERGY LLC– 10770**

**Location Name: BEAR GULCH -FEDERAL #19-4**

**Location ID: 322362 API #: 05-045-06116**

**Inspection Date: 7/15/2024 Inspection Doc#: 693807483**



**Separator**



**Meter housing and blowdown pit.**