

# Inspection Photos

July 9th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 313480

Inspection Document #: 714000956

Montezuma County, CO

Township: SWSW 23 37N 18W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: McElmo Dome Unit 23-13-18 YB 1

Location ID: 313480



7/9/24

+37.445187,-108.806762

297° NW



Inspection Photos

Location Name: McElmo Dome Unit 23-13-18 YB 1

Location ID: 313480



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the western portion of the interim reclamation area that remains mostly bare with sparse vegetation.

API #: 083-06252



Inspection Photos

Location Name: McElmo Dome Unit 23-13-18 YB 1

Location ID: 313480



**Photo 3.** Reference are comprised of Crested wheatgrass, Rabbitbrush and juniper.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 083-06252