

Inspection Photos

July 9th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 313505

Inspection Document #: 714000957

Montezuma County, CO

Township: NWSW 23 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McElmo Dome Unit 23-37-18 YB 3
Location ID: 313505

7/9/24
+37.446782,-108.807195
339° N



Photo 1. View of the well pad taken from the access point facing center.



7/9/24
+37.446622,-108.807249
26° NE

KINDER MORGAN
CO₂ COMPANY, LLC
McELMO DOME UNIT YB-3
SEC. 23, T37N, R18W
1782' FSL & 805' FWL
LEASE NO. C-11645-A
MONTEZUMA COUNTY, CO
EMERGENCY PHONE # 970-882-5522 011

API #: 083-06375

Inspection Photos

Location Name: McElmo Dome Unit 23-37-18 YB 3

Location ID: 313505



7/9/24

+37.447403,-108.807230

13° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Unused equipment corrective action identified in the previous inspection doc #693901441 has been addressed/resolved.

API #: 083-06375

Inspection Photos

Location Name: McElmo Dome Unit 23-37-18 YB 3

Location ID: 313505



7/9/24

+37.447394,-108.807090

138° SE

Photo 3. View of the eastern interim reclamation area facing south west.



Inspection Photos

Location Name: McElmo Dome Unit 23-37-18 YB 3

Location ID: 313505



7/9/24

+37.447687,-108.807107

354° N

Photo 4. Reference are comprised of Juniper, Big sage brush and Broom snakeweed.

