

Inspection Photos

July 9th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 432958

Inspection Document #: 714000959

Montezuma County, CO

Township: NWNE 12 37N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: YA 8
Location ID: 432958

7/9/24
+37.483323,-108.779647
291° W



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: YA 8
Location ID: 432958

7/9/24
+37.483271,-108.780204
78° E



Photo 2. View of the southern interim reclamation area facing east.

Inspection Photos
Location Name: YA 8
Location ID: 432958

7/9/24
+37.483356,-108.780454
246° SW



Photo 3. View of surface owner boats/trailers stored in the southwest corner of the disturbance.