

Operator: BCEI
Location Name: Antelope F-18
Loc ID: 429686
Inspection: 696306503



Exhibit A



Exhibit B

CA: F-J-18HNB Well Sign has faded no longer visible; see photos Install sign to comply with Rule 605.d.

CA Resolution: Operator has reported that the signage has been updated and appropriately installed to comply with Rule 605.d.