

Operator: XOG

Location Name: Arellano 10-L Facility

Loc ID: 440776

Inspection: 708201213



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F

CA: Tank labels and signs are faded, peeling, cracked. Refer to attached inspection photos for examples. Install sign to comply with Rule 605.g.

CA Resolution: Operator has reported that the labels have been replaced and installed appropriately to comply with Rule 605.g.