

Inspection Photos

July 12th, 2024

Operator: Kinder Morgan CO2 CO - 46685

Location ID: 313569

Inspection Document #: 714000968

Montezuma County, CO

Township: SENW 7 36N 18W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sand Canyon 9
Location ID: 313569



7/12/24
+37.651528,-109.407581
6° N

Photo 1. View of the well pad taken from the access point facing center.



7/12/24
+37.393937,-108.874390
14° N

KINDERMORGAN
CO₂ COMPANY, LLC
McELMO DOME UNIT-SAND CANYON 9
SEC. 7, T36N, R18W
3308' FSL & 2342' FWL
LEASE NO. C-19737
MONTEZUMA COUNTY, CO
EMERGENCY #970-882-5522 OR 911

Inspection Photos
Location Name: Sand Canyon 9
Location ID: 313569

7/12/24
+37.651528,-109.407581
178° S



Photo 2. View of the western interim reclamation area facing south.

Inspection Photos
Location Name: Sand Canyon 9
Location ID: 313569

7/12/24
+37.651528,-109.407581
258° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of reference area comprised of Juniper, Broom snakeweed and Indian ricegrass.

API #: 083-06573