

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Photo # 3015 From entrance to location

Photo # 3016 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Photo # 3017 Location



Photo # 3018 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Jul 18, 2024 at 11:37:32 AM
CO



Jul 18, 2024 at 11:38:17 AM
CO

Photo # 3019 Location

Photo # 3020 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LARAMIE 20-12 Pad

Location ID: 335520



Photo # 3021 Small amount of staining in secondary containment