

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403815917

Date Received:

06/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kilian Collins

kilian.collins@state.co.us

Kyle Waggoner

kyle.waggoner@state.co.us

Krystal Heibel

krystal.heibel@state.co.us

Abdul Elhajdi

abdul.elhajdi@state.co.us

Dolezal, Pat

970-332-3585

pat.dolezal@ownresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100278

Inspection Date: 04/24/2024

FIR Submit Date: 05/07/2024

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 337785

Location Name: KNODEL-64S42W Number: 17NENE County: _____

Qtrqtr: NENE Sec: 17 Twp: 4S Range: 42W Meridian: 6

Latitude: 39.716090 Longitude: -102.087470

FACILITY - API Number: 05-125-00 Facility ID: 337785

Facility Name: KNODEL-64S42W Number: 17NENE

Qtrqtr: NENE Sec: 17 Twp: 4S Range: 42W Meridian: 6

Latitude: 39.716090 Longitude: -102.087470

CORRECTIVE ACTIONS:

1 CA# 194946

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 07/07/2024

Response: CA COMPLETED

Date of Completion: 05/10/2024

Stained soil was removed and replaced with clean soil

2 CA# 194947

Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This information shall be submitted within the next Form 27 submittal.

Date: 07/07/2024

CA COMPLETED

Date of Completion: 05/10/2024

Soil samples have been taken for rem#34584
--

--

3 CA# 194948

Comply with Rule 606

Date: 05/14/2024

CA COMPLETED

Date of Completion: 05/10/2024

No growing tumbleweeds were observed by area foreman when inspected

OPERATOR COMMENT AND SUBMITTAL	
--------------------------------	--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Pat Dolezal

Signed:

Regulatory Specialist

Date: 6/6/2024 11:28:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403815917	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files