

Final Reclamation and Stormwater Inspection

Date: 7/9/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 330347

Inspection Document #: 713900781

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: HSR-Acord #13-29
Location ID: 330347



Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates the location is dominated by Kochia, Russian thistle and bare soil.

Inspection Photos
Location Name: HSR-Acord #13-29
Location ID: 330347



Photo 2. The photo was taken at the well location facing North. The photo illustrates the access road road remains.

Photo 3. The photo was taken at the well location facing East. The photo illustrates the well location itself appears to meet final reclamation requirements.



Inspection Number: 713900781

Inspection Photos
Location Name: HSR-Acord #13-29
Location ID: 330347



Photo 4. The photo was taken at the well location facing South. Refer to the comment for photo 5.



Photo 5. The photo was taken at the well location facing West. Refer to the comment for photo 6.

Inspection Photos
Location Name: HSR-Acord #13-29
Location ID: 330347



Photo 6. The reference photo was taken North of the well location facing West.