

Final Reclamation and Stormwater Inspection

Date: 7/9/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 437337

Inspection Document #: 713900783

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Acord State Tank Battery

34N-30HZ

Location ID: 437337



Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates the location is dominated by Kochia, Russian thistle and bare soil.

Photo 2. The photo was taken at the tank battery location facing East. Refer to the comment for photo 1.

Inspection Photos

Location Name: Acord State Tank Battery

34N-30HZ

Location ID: 437337



Photo 3. The photo was taken at the tank battery location facing South. Refer to the comment for photo 1.

Photo 4. The photo was taken at the tank battery location facing West. Refer to the comment for photo 1.

Note - One meter shed remained at the tank battery location.