

Work Completion Report

Contractor: Northern Colorado Constructors (NCC)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
JUDY 1 43-27	July	Lawrance Moir	7/18/2024

Work Summary	Reclamation Type	Land Use
Spread topsoil, drill, seed, import road base, crimp, straw	Final	Pasture

One-Call Number	Red Zone Rep	Red Zone Date
	Scott Taylor	7/16/2024

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Evaluate and complete final reclamation practices	Normal	No	Location(s): JUDY 43-27 1 Notes: Remove roadbase from berms and spread on the east west access road, bring one load of topsoil down with truck. Deep rip, disk, seed and mulch berm area. Seed north south access road on way out. Take very good photos of east-west access road once roadbase from berms is spread as there will be a variance on that access road. Coordinate with Scott prior to going down.

COMPLETION DETAILS

Total Area Affected: **10,890 sq ft**
 Seed Mix: **Sandy Initial (4.24 lbs)**
 Crop Type:
 Soil Type: **Sandy Loam**
 Stabilization Date:
 Seeding Date:
 Mulch: **None**
 Straw Bales: **NA**
 Soil Amendment Type: **none**
 Soil Amendment Rate: **NA**
 Imported Top Soil: **39.00 Tons**
 Top Soil Source: **Hunt**
 General Notes:

PHOTOS

Photo Name: Site Map

Description:



Photo Name: Seed Mix

Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: D1

Description:



Photo Name: D2

Description:



Photo Name: D3

Description:



Photo Name: L1

Description:



Photo Name: L2

Description:



Photo Name: TS1

Description:



Photo Name: TS2

Description:

