

Inspection Photos

07/18/2024

Operator: ANSCHUTZ EXPLORATION CORP
#3104

Location ID: 430926

Inspection Doc: 696205997

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926



Photo 1: Stained soils have not been cleaned/remediated. Leak at pipe observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: ANSCHUTZ EXPLORATION CORP #3104

Location ID: 430926




Photo 2: Stained soils at/beneath methanol tank remains evident.