

Inspection Photos

07/18/2024

Operator: WINDSOR ENERGY GROUP LLC

#10081

Location ID: 398460

Inspection Doc: 696205999

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 398460



Photo 1: Photos 1-2 taken from the central areas of the Location. Photos provide an overview of the site from north, east, south to west. Vegetation observed in photos appears to be predominantly Broom Snakeweed



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 398460



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 398460



Photo 3: Photo shows soil/rocks/material and trash debris that remain stockpiled on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources